

# 2018 Nissan Altima P0420 Code

**2018 Nissan Altima P0420 Code** - Learn what does P0420 Nissan Catalyst System Efficiency Below Threshold Bank 1 means? ... 2001 Nissan Frontier-Xterra Factory Service Bulletin OBDII Code P0420 2004 Nissan Altima 2005 Nissan Altima ... Posted and Edit by AutoCodes.com 08-20-2018 ... This page is meant to help you troubleshoot the Nissan Altima P0420 trouble code. It covers Nissan Altima P0420 meaning, symptoms, causes, and possible solutions. With the Altima, OBDII P0420 is often caused by a bad oxygen sensor, but there can be other causes as well. 12/27/2018. Nissan Mechanic: ... i have a 2006 nissan altima i am getting code 420 on my scanner any thoughts i can not find that code in my book ... I have a 2002 nissan Altima and just got P0420 code. The manual is telling me that its the cat bank 1. My 2005 Nissan Altima 2.5 L has a P0420 code error (Catalyst System Efficiency Below Threshold Bank 1). So far I changed the spark plugs, upstream and downstream ...